





Coastal Inspection Pros

PO Box 110942 Naples, Florida 34108 Phone: 239-238-4322 www.CoastalInspectionPros.com

Four-Point Inspection



123 Example Ln Naples

Prepared for Demo Dan

Licensed to:

Kris Beall
License #HI13231

Inspector: Kris Beall

4-Point Inspection Form

Insured/Applicant Name: Demo Dan		Applicati	on / Policy #:		
Address Inspected: 123 Example Ln		Naples	33999		
Actual Year Built: 2011	ar Built: 2011 Date Inspected: Dec 10, 2020				
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present of the single strand (aluminum branch) wiring Connections repaired via COPALUM crimical Connections repaired via AlumiConn	g, provide details of all rem		cumentation of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing General condition of the electrical system:		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
Content Condition of the Clourious System.					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 11 Years	Panel age:		Copper		
Year last updated: 2011	Year last updated:		NM, BX or Conduit Other		
Brand/Model: Square D	Brand/Model:				

Insp4pt 01 18 Page 1 of 9

Inspector: Kris Beall

4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of system: 11 Years Year last updated: 2011 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsati	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Yes Original to home No Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

Insp4pt 01 18 Page 2 of 9

Inspector: Kris Beall

4-Point Inspection Form

Roof (With photos of each roof	slope, this section can take	the place of the Roof Inspec	ction Form .)		
Predominant Roof		Secondary Roof			
Covering material: Concrete		Covering material:			
Roof age (years): 11 Years		Roof age (years):			
Remaining useful life (years):	15-20 Years	Remaining useful life (years):			
Date of last roofing permit: Jan 1, 201	1	Date of last roofing permit:			
Date of last update:		Date of last update:			
If updated (check one):		If updated (check one):			
☐ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
Satisfactory		Satisfactory			
☐ Unsatisfactory (explain below)		Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Original roof					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
n lace	Home Inspector	License #HI13231	Dec 10, 2020		
Inspector Signature	Title	License Number	Date		
Coastal Inspection Pros		Home Inspector	239-238-4322		
Company Name		License Type	Work Phone		

Insp4pt 01 18 Inspector: Kris Beall Page 3 of 9

Inspector: Kris Beall 4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Kris Beall Page 4 of 9

123 Example Ln Naples



Front Elevation



Side Elevation



Rear Elevation



Side Elevation



Outside Electrical Box



Electrical Box Data Tag - 2011



Inside Electrical Box



Water Main Shut Off



Plumbing - Kitchen Sink



Plumbing - Master bath left sink



Plumbing - Master bath right sink



Plumbing - master bath toilet valve



Plumbing - #2 bath sink



Plumbing - #2 bath toilet valve



Plumbing - laundry sink



Washing Machine Outlet Box



Water Heater



Water Heater Data Tag - 2020

123 Example Ln



Water Heater T&P Valve



Roof



Roof



Roof



Roof



Roof



Roof



Roof



AC Air Handler



AC Air Handler Data Tag - 2011



AC Condenser



AC Condenser Data Tag - 2011